

| REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE <i>(EP 1130-2-520)</i> | | | | | PAGE 1 OF 1 | | |
|---|----------------|------------------------|--------------------------|---|--|------------------------------|--|
| | | | | | DATE 3 September 2008 | | |
| TO: Navigation Interests | | | | FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715 | | | |
| RIVER/HARBOR NAME AND STATE Susquehanna River Harford County, Maryland | | | | | MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD | | |
| NAME OF CHANNEL | DATE OF SURVEY | AUTHORIZED PROJECT | | | LEFT OUTSIDE QUARTER <i>(feet)</i> | MIDDLE HALF <i>(feet)</i> | RIGHT OUTSIDE QUARTER <i>(feet)</i> |
| | | WIDTH <i>(feet)</i> | LENGTH <i>(miles)</i> | DEPTH <i>(feet)</i> | | | |
| Susquehanna River 0+000 to 22+018.90 Surveyed on 26 August 2008 | | 200 | 4 | 15 | 12 | 11 | 10 |
| | | | | | | | |
| REMARKS <i>(Continue on reverse)</i> all depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. Length of channel is reported to the nearest mile. Actual length is 4.17 miles. All depths are reported to the nearest foot. LQ=E1569674.20, N668793.47 (12.4') MH=E1569810.35, N669088.81 (11.3') RQ=E1569838.63, N668882.50 (10.3') | | | | | | | |